



For best results, clean the sensor with mineral spirits.

Operating Instructions:

1. Press the ON/OFF button to power on the gauge.
2. To manually power off the gauge, press and hold the ON/OFF button until the screen displays the "YJ" logo.
3. To change a setting:

- Tap the corresponding button to highlight the current setting.
- Continue to tap this button until the desired value is displayed.
- Press and hold this button to confirm the new setting. The highlighting will disappear when the setting has been confirmed.

***DISPLAY** - Select from several notification options. To change the background, press and hold for three seconds to inverse LCD mode.

***ON/OFF** - Power on and off, select from four different auto-off timer settings.

